


# Interstate Designation Issues



## VERTICAL CLEARANCE DEFICIENCIES

**Disclaimer Statement:**  
**This is not a proposal**

This is a display of vertical clearance deficiencies for bridge structures if strict Interstate standards were applied.  
Future negotiations with the U.S. Department of Transportation may eliminate some or all of the listed locations.



Tag #	PM	Location Description
79	R53.82	Mendocino Ave OC
80	51.81	Dodge Avenue OC
81	48.71	Merrit Drive OC
82	40.67	Goshen OC
83	36.41	Avenue 280 OC
84	33.96	Tagus OC
85	33.22	South Tagus OC
86	31.78	Cartmill Road OC
87	30.54	Prosperity Ave OC
88	29.79	Tulare UP
89	29.55	Route 137/99 Sep
90	28.59	Bradsley Ave OC
91	27.60	Paige Road OC
92	26.05	N99-K St Off-Ramp OC
93	25.40	Ave 200 OC
94	23.46	Avenue 184 OC
95	19.46	Avenue 152 OC
96	18.93	Sixth Street OC
97	18.43	Route 190/99 Sep
98	12.76	Avenue 100 OC
99	12.60	Davis Ave OC
100	10.29	Avenue 80 Poc
101	7.16	Avenue 56 OC
102	6.63	Washington St OC
103	6.09	Avenue 48 OC

